Drake Air Inc.

4085 Southwest Blvd.

Tulsa, Oklahoma 74107

(918) 445-3545

Repair Station No. II2R899Kl div 23mapro22A al baluaria 200 hariages.

less. Date	Meds		Description	Dept.	qe) .or
74/12	W	ende exar er ense contamination, ensigns,	Receive and impact units in following: Engrave unit with Work order Number Visually entreet und for damage to under in- provious result and note findings on in-Reseived with the units wife supers received with the units wiperopness work order.	Rest Inpe	
3/1/6	97	egarok oʻz anoti sain is gabit ina oʻlkmoʻ	Remove all Misc Rems. Valve, 's its oriton para i and admits with empropriate work order num.	Rat	
18/1/2	30	Dinke Ar tea filtre, star feurle	Terrorial the documental second to the West St.	3.0	
Stile.	90		Clear Figure units in secondar 5 with DAF-1000 with mode.	379	
			traped and to brack dank din or paopage and	21	
39.(6)	-8-2	capite filter for the calcondate products	The temporal count business to under a made and the country of a manufact and inspect for leading. Note: The country of the c		
	A.A.		100 t-4A/G WAL	% के किया	
REPAIR_	, ASA	The is X-Ray of inspectanceally a for internal and a sum of an analysis of the other and a sum of the course of th	The process of the process is the many case. BENCH CHECK	Risp Insp	
	The state of the s	3 and/ of the stached open then sheet if	Repair and progress units IAW DAF-1002, DAF-10	qsal	

Serviceable Part Maintenance Release

Aircraft, Airframe, Aircraft Engine I ropeller or Appliance Identified on the front side of this Document Was repaired And Inspected In Accordance With Current Regulations Of The Federal Aviation Agency And Is Approved For Return To Service.

Pertinent Details Of The Repair Are On File At This Repair Station.

21234

Date MAR 1 9 1996

Signed Joseph Suit

Checentery Herz

0901

A-10 \ box

Repair Station No. without light

112R899K

Rap Jang

Acott mos

Britis.

W.O. -

muses all miscelles outs pieus parts; Valves, part to ensure sale delivery to the customer I.

FVA Charles 08.7

Drake Air Inc.

Repair Work Ord

Heat Transfer Products ENGINE OIL COOLER

Doc# EJN0002956

Batch

Repair Station II2R899K

Work Order	21234	Customer	EVERGREEN HELI
Part Number	13.85 294B	Serial Number	1060
Туре	TUBE TYPE SECAN	Purchase Order No.	
Customer Instructions		LETENCE CALL IN	
Inspection Notes	I value, DEM TAGE	E T T 小 直接 など 「	
		CS-CWE (CTA)	

Repaired / Overhauled In Accordance With Drake Air Process DAP-1002 DAP-1003 and / or-

Step No.	Dept.	Description	Mech	Insp.	Date
1	Rec / Insp	Receive and inspect units as following: Engrave unit with Work order Number Visually inspect unit for damage to internal threads, exterior case, contamination, cracking, previous repair and note findings on the Receiving / Inspection log All misc piece parts received with the units will be bagged stored and identified with the appropriate work order	en		3/4/4
2	Rep	Remove all Misc items; Valves, bolts, carbon parts from the unit. Bag all misc items for storage and identify with appropriate work order number	CR		3/4/46
3	Rep	Remove all gasket material excess oil ect. and install Drake Air test fittings as applicable	CR		3/4/96
4	C/L	Clean / Flush units in accordance with DAP-1000 and / oras applicable	ce	*	3/4/96
5	Insp	Inspect unit for leaks, dents, dirt or blockages and :			7//12
		If no manual exist Submerge unit in water and apply 100 PSIG air (or nitrogen) pressure for 3 minutes and inspect for leaks. Note Findings: Tabe + Hendel Cenks	Sa	O5	3-54
6	Weld	Weld repair as necessary IAW DAP-1001	who		
7	Rep / Insp	X-Ray unit only if directed by the customer. If unit is X-Rayed inspect negative for internal blockage or contamination. Any signs of blockage shall cause the unit to repeat steps 4 and 5 herein.	who		EPAIR
8	Rep	Repair and process units IAW DAP-1002, DAP-1003 and/or the attached operation sheet if applicable and/or OEM overhaul manual	Same and	a carrier se	3158
9 of the state of	Rep / Insp	Final Test: Test unit IAW applicable overhaul manual and note test pressures. If no manual exists test IAW DAP-1002 / DAP-1003 and note test pressure below: Pressure tested at	Som	05 05	210.2
10	Rep 10 1 ha	• Fly cut mounting surfaces as applicable to ensure a flat surface. Surface must be flat within .006	1ha	n beto	quel has
11	Rep / Insp	If Applicable perform thermostatic and relief valve testing IAW applicable overhaul manual and record results: Measured "cold" Measured fully extended When the supplicable overhaul manual and record results:	251 cart 1	(FA)	3-146
12	Rep	Paint exterior surfaces with corrosion protection coating and paint.	0,1		2991
13	Ship / Insp	Visually inspect the part for satisfactory repair and assembly . Ensure all appropriate documentation; Identification, maintenance release, 8130-3 etc is properly completed.	Q	(05)	7178
14	Ship / Insp	Install protective caps in all threaded locations, identify part with a Drake Air repair tag and ensure all miscellaneous piece parts; Valves, fittings, bolts etc. are returned with the part. Package part to ensure safe delivery to the customer IAW best commercial practice.		65° 05°	3-12-92