


AOG Reaction

526 Aviator Drive
Fort Worth, TX 76179-5425

SERVICEABLE PART**F.A.A. REPAIR STATION TU1R519K****(817) 439-0700****FAX (817) 439-9700**

| | | | | | | | |
|--|------------------------------------|---|---|---|--------------------------|--|--|
| 1. Approving National Aviation Authority/Country: FAA/UNITED STATES | | 2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG | | | | 3. Form Tracking Number: 61472 | |
| 4. Organization Name and Address: AOG Reaction, Inc. 526 Aviator Drive, Fort Worth, TX 76179 | | | | | | 5. Work Order/ Contract/Invoice Number: W.O.# 61472 | |
| 6. Item: | 7. Description: | 8. Part Number: | 9. Eligibility: | 10. Quantity: | 11. Serial/Batch Number: | 12. Status/Work: | |
| 1 | Circuit Breaker Eaton Aerospace | SM600BA50N1 | N/A | 1 | 41849 | INSPECTED | |
| 13. Remarks: Description of Work Performed: CLEAN INSPECT & TEST PER SM600BA REV 08/04/99 MEETS OEM SPECIFICATIONS See Teardown/Analysis Report for further details *Certifies that the work specified in block 12/13 was carried out in accordance with JAR 145 and with respect to that work the aircraft component is considered ready for release to service under JAA Acceptance Certificate Number: JAA.4164 | | | | | | | |
| 14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13. | | | 19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work the items are approved for return to service. | | | | |
| 15. Authorized Signature: N/A | | 16. Approval/Authorization No: N/A | | 20. Authorized Signature:  | | 21. Approval/Certificate No: TU1R519K | |
| 17. Name (Typed or Printed): N/A | | 18. Date (m/d/y): N/A | | 22. Name (Typed or Printed): Robert Samson | | 23. Date (m/d/y): 08/21/02 | |

TEARDOWN/ANALYSIS REPORT**Customer:** Evergreen Helicopters**Customer's RO:** R-39806**Customer Agent:** Marilyn Langeback**Date received:** 08/13/02**Part Number:** SM600BA50N1 **Serial number:** 41849**Part Nomenclature:** Circuit Breaker**Manufacturer:** Eaton Aerospace**Removed From:** EVERGREEN HELICOPTERS STOCK**Time on Part:** NTC**Defect Reported:** AIRWORTHINESS INSPECTION**Defect Confirmed?:** N/A **AD Notes, Service Bulletins Applicable:** None**Shop Inspection/Test Findings:** TESTED OK. NO DEFECTS NOTED**Work Accomplished:** CLEAN INSPECT & TEST PER SM600BA REV 08/04/99
MEETS OEM SPECIFICATIONS**Remarks:**
R/O CALLS OUT PARTIAL P/N SM600BA**526 Aviator Drive • Fort Worth, TX 76179-5425 • (817) 439-0700 • Fax (817) 439-9700**