


Company:
Address:

Receiver #: R5970
Order #: PC-E PC1322
Entered: 12/22/2022
SJB

Part Number	NSN	Qty	Qty Appr	Qty Rej	Cond	Location	Control #	ID	Serial #	Hologram #
Description		Max Qty	Qty Appr Hist	Qty Rej Hist	Consign	Warehouse				
3011095		1.00	1.00	0.00	OH	C-R2-B25				
SHAFT, PT		0	0.00	0.00	_	WHS1	11700	1	RWA40A010	

Findings for S/N #RWA40A010

Findings:

1. Approving National Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: W5301-86298	
4. Organization Name and Address: Midwest Turbine Service 4200 County Highway U Hartford, WI 53027					FAA CRS DATR119D EASA.145.6619		5. Work Order/Contract/Invoice Number: W5301
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:		
1	Power Turbine Shaft	3011095	1	RWA40A010	OVERHAULED		
12. Remarks: Notes: The service indicated in Block 11 has been performed in accordance with Overhaul Manual part number <u>3021243</u>, Revision <u>49</u>, Dated <u>Oct 04/2021</u> and the item is approved for return to service. All pertinent details of work performed can be found in work order identified in Block 5. The part listed in block 8 was removed from engine serial number <u>PS PC1322-100</u> MTS certifies that work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work, the article is considered ready for release to service under EASA Part-145 Approval Number: EASA.145.6619							
TSN <u>N/A</u> CSN <u>N/A</u> TSO <u>0.00</u> CSO <u>00</u>							
13a. Certified and approved for return to service in accordance with the following: 13b. Approved design data and are in accordance for safe operation: 13c. Non-approved design data specified in Block 12:				14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13d. Authorized Signature: 13e. Approval Station/Address: 13f. Name (Typed or Printed): 13g. Date (dd/mm/yyyy):				14b. Authorized Signature:  14d. Name (Typed or Printed): Garrett S. Timothy		14c. Approval/Certificate No.: DATR119D	
13h. Name (Typed or Printed): 13i. Date (dd/mm/yyyy):				14e. Date (dd/mm/yyyy): 13/Oct/2022			
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							