1.Approving National Aviation Authority/Country: FAA/UNITED STATES		2.	AUTHORIZED FAA FORM 8130-3,	3. Form Tracking Number: W4387-70980								
4. Organization Name and Addre			Midwest Turbine Service 4200 County Highway U Hartford, WI 53027		FAA CRS DA EASA.145.66	· · · · · - -	5. Work Order/Contract/Invoice Number: W4387					
6. Item:	7. Description:		8. Part Number:	9. Quantity:		10. Serial Number:	11. Status/Work:					
1	Power Turbine Share	ft	3107255-01	1		5020-486	OVERHAULED					
12. Remarks:												
Notes:												
The service indicated in Block 11 has been performed in accordance with Overhaul Manual part number 3032843. Revision 48. Dated May 28/2018 and the item is approved for return to service. All pertinent details of work performed can be found in work order identified in Block 5. The part listed in block 8 was removed from engine serial number PS 32307 MTS certifies that work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work, the article is considered ready for release to service under EASA Part-145 Approval Number: EASA.145.6619												
				-	· ·							
TSN N/A	CSN_	N/A	TSO	_ cs	O 00							
14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 2 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved return to service.												
Chr. Gulleringe: Pripagilia				14b. Authorized Signature:			14c. Approval/Certificate No.:					
				toldstake			DATR119D					
				~~~~	Name (Typed or Pr	inted):	14e. Date (dd/mmm/yyyy):					
				Tod	d R. Bleecker		06/Jun/2019					
10000000000000000000000000000000000000	<u> </u>	*****	User/Inst	aller Resp	onsibilities							
1			nce of this document alone does not au		1							
Block 1, it is specified in	s essential that the user/ir Block 1.	staller		ority accept	s aircraft engine(s)/pro	opeller(s)/article(s) from	the airworthiness authority of the country					
Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.												

Av-Eng Aero Ltd.

QA Document

Company:			-		Receiver #: R6647				
Address:					Order #: PCE-32232/PS32307				
					Entered: 6/14/2023				
Part Number NSN	Qty	Qty Appr	Qty Rej Cond	Location	Control #	ID	Serial #	Hologram #	
Description	Max Qty	Qty Appr Hist	Qty Rej Hist Consign	Warehouse					
3107255-01	1.00	1.00	0.00 OH	A-R2-B27					
HOUSING ASSEMBLY, POWER TURBINE SHAFT	0	0.00	0.00 _	WHS1	13204	1	5020-486		
Findings for S/N #5020-486									
Findings:									
		•		 					
		· · · · · · · · · · · · · · · · · · ·							